- BASE WIRING SHOWN WITHOUT CONTROL RELAY. WHEN CONTROL RELAY IS USED, WIRES SHOWN CONNECTED TO "A" AND "B" ON SWITCH ARE REMOVED, SPLICED TOSETHER AND TAPED. WIRE LOOPS AT SWITCH AND CONTROL RELAY COIL ARE CUT AND CONNECTED TO RESPECTIVE UNITS. WIRE LOOP AT CONTROL RELAY CONTACTS IS CUT, "8" IS CONNECTED TO "E" FOR "BREAK OPER." AND TO "C" FOR "MAKE OPER". "F" IS CONNECTED TO "D" IN EITHER CASE.
- 65 TO 66; REMOVE AND TAPE GREEN WIRE GOING TO LINE RELAY FROM TERMINAL 61.
- .020 AMP. SIGNAL LINE OPERATION, CONNECT THIS LEAD TO OTHER TERMINAL OF RESISTOR

OR FUSTAT

110 V. AG-60 GYGLE SYN. * 3.2 AMP. 6 AMP.

110 V. DG GOV. 1.60 AMP. 3 AMP.

110 V. OG GOV. 8 AMP. 3 AMP.

110 V. AG-25 CYGLE GOV. 1.4 AMP. 3 AMP.

**A 3.2 AMP. FUSETRON IS FURNISHED WITH NEW IS PTR. BASES

- 6. TO DISABLE SEND-RECEIVE BREAK MECHANISM
 - A. SPLICE AND TAPE WIRES MARKED "X". TAPE WIRE MARKED TY".
 - C. SPLICE AND TAPE WIRES MARKED "Z"
- WHEN A.C. SERIES MOTOR IS TO BE DRIVEN FROM 25 CYCLE POWER SUPPLY, A 25 OHM RESISTOR SHOULD BE CONNECTED IN THE


- RY-28 RELAY (W.E. 215-H) 85 OHMS PER WINDING. (FOR .OGO AMPERE SIGNALING ONLY) RY-30 RELAY (ME. 255-A) -136 OHMS PER WINDING. (FOR .060 OR .020 AMPERE SIGNALING)

74786 A.C. MOTOR UNIT 74672 KEYBOARD & PERF. TRANS. 74573 BASE (POWER) 74625 SELECTOR MAGNET 74576 LINE RELAY UNIT


99881 PERFORATOR & COUNTER (PERF. TRANS.)

- ALL WIRES ARE NO. 18 DELTABESTON COTTON COVERED FIXTURE WIRE, EXCEPT MOTOR LEADS.


RTTY ELECTRONICS TELETYPE=Sales-Service-Parts PO Box 20101 El Sobrante, Ca. 94820. (510)222-3102 mr_rtty@pacbell.net




ACTUAL WIRING 15 PRINTER SET WITH KEYBOARD



ACTUAL WIRING - 15 TYPE PERFORATOR TRANSMITTER (CHARACTER COUNTER UNIT MOUNTED ON PUNCH ASSEMBLY TO THE LEFT OF KEYBOARD.)



SCHEMATIC WIRING - 15 PRINTER SET WITH KEYBOARD



CORPORATION WD-1986-W